

WEST MAKASSAR MAIN DRAINAGE FLUSHING OPERATION PROCEDURE DEVELOPMENT

Melly Lukman^{*)}, Mukhlis Ahmad^{**)}

ABSTRAK

Sistem drainase utama yang mencakup hampir seluruh bagian barat dari kota lama Makassar, vang terhubungkan dengan sungai Jeneberang melalui waduk pantai dengan kapasitas 5 m³/detik - 30 m³/detik. Pada beberapa bagian dari sistem ini menumpuk kotoran dan sedimen. Tulisan ini mencoba untuk mengembangkan sistim pengoperasian yang akan menjadi acuan untuk penggelontoran dalam upaya memperbaiki kondisi lingkungan. Metode penggelontoran dilakukan sebagai berikut : 1) Persiapan 2) Pengambilan contoh air sebelum pintu penggelontor dibuka, pintu kontrol ditutup 3) Penggelontoran selama 24 sampai 28 jam 4) Pengambilan contoh air saat setelah 24 jam - 28 jam penggelontoran, kemudian pintu penggelontor ditutup 5) Sistem drainase berjalan seperti biasa selama 24 sampai 48 jam 6) pengambilan contoh air 7) Test contoh air 8) Evaluasi kualitas air. Penggelontoran dilakukan sselama 3 hari untuk keseluruhan sistem drainase,; Jongaya, Sinrijala dan Panampu, serta tes laboratorium untuk sample air yang diambil sebelum dan sesudah penggelontoran. Kualitas air di akhir hari pertama penggelontoran menunjukkan perubahan yang signifikan. Akan tetapi sehari setelah penggelontoran berakhir, kualitas air menunjukkan cepatnya kembali ke kondisi awal. Berdasarkan sistem penggelontoran dan test laboratorium dan evaluasi yang dilakukan, maka direkomendasikan sistim penggelontoran sebagai berikut : 1) Penggelontoran harus dilakukan secara menerus selama 2 hari untuk setiap operasi penggelontoran 2) Penggelontoran perlu dilakukan setiap 2 minggu sekali selama musim panas 3) Exercise ini harus dilakukan selama musim panas untuk dapat diperoleh sutu prosedure permanen sistim penggelontoran.

Kata Kunci : Penggelontoran, Sistim Pengoperasian, Sistem Drainase, Dampak Lingkungan

INTRODUCTION

For many years Makassar has experienced flood problems. One of the most devastating floods occurred on January 13, 1986. the flood water covered most of the west and eastern parts of the city and has caused a huge damage to the city infrastructures, public facilities, as well as on the resident areas.. Jongaya, Panampu and Sinrijala drainage channels (see Figure1) were

^{*)} Engineering Faculty of Paulus Christian University of Indonesia Makassar

Telp : 081 242 76145, <u>mellylukman@yahoo.com</u>

^{**)} Deputy Head of Dinas PSDA South Sulawesi

constructed in 1993. Total length of the channels (Jongaya-Panampu-Sinrijala is about 13,870 km, with inspection roads of about 13,870 km, drainage culverts (34 box units, 291 pipe units), control gates (4 units), and fence (14,995 km).

In the course of its existence, city government has not paid serious attention to the urban drainage channels (Jongaya, Panampu and Sinrijala), particularly for control of garbage dumping into the channels. Therefore, water turned out to be blackish in dry season, the smell was reeking and offensive to surrounding area. In addition, many citizens at slum areas were using groundwater from shallow well for shower (not for drinking water) along the drainage channels.

In order to reduce smell and to dilute the water of the channels, test operation of flush gate was carried out. Test operation for Jongaya drainage channel was held in July 2006. Since SNVT Pengendalian Banjir dan Pengamanan Pantai Sulawesi Selatan (South Sulawesi Flood Control and Coastal Protection Project) has dredging works at Panampu drainage channel in 2006, test operation could not be held in July 2006 concurrently with the test operation of Jongaya drainage channel. The test operation for Panampu and Sinrijala just can be held in November 2006.

MAKASSAR MAIN DRAINAGE SYSTEM AND OTHER FACILITIES (FIGURE 1 AND FIGURE 2)

Rubber Dam

Rubber Dam is made of the inflatable rubber-made body with the five gates, which have the crest level of EL. 1.8m and the entire width of 210m. The Dam is located 3.65 km upstream from the river mouth playing a role to prevent salinity water from intruding to Lower Jeneberang River and its adjacent Long Storage.

According to the original operation rule, the Rubber Dam is to be fully inflated maintaining its maximum dam crest level of EL. 1.8m during a dry season in order to shut the river flow toward the river mouth and to let the whole river flow into the Long Storage. However, when the test operation was made in this dry season, the Dam was slightly deflated maintaining the dam crest level of EL. 1.70m and allowed the dam overflow toward the river mouth. It was understood that the overflow was required to cool the dam body of rubber in accordance with instruction from the supplier of the Rubber Dam.

Long Storage

Long Storage is a water-storage channel of 5.26 km in length and 150m in width, which is connected to the right bank of the main channel of Jeneberang River about 350m upstream from Rubber Dam. Long Storage has an effective storage capacity of 1.6 million m3 to store the fresh water diverted from Jeneberang River. The water stored in Long Storage is used as water supply source for municipal demand, water source to dilute the water in the three drainage channels, namely Jongaya, Panampu and Sinrijala and, amenity space.

Long Storage is equipped with one inlet gate from Jeneberang River and two outlet gates of Flush Gate at the right bank about 1.5km downstream from the inlet gate of Long Storage and, Tidal Gate at the downstream end of Long Storage. The present operation rule allows opening the Flush Gate, when the water level of Long Storage is between El. 1.00m (LWL) and El. 1.8m (NHWL). In accordance with the operation rule, the water level of Long Storage was maintained at EL. 1,58 -1.6m during the 2-day period of test operation through the following operations for the inlet and outlet gates:

- (a) The Tidal Gate was closed and the Inlet Gate fully opened in order to keep the higher water level of Long Storage.
- (b) The Flush Gate opened with gate opening height of 0.80m for two consecutive days.

Flush Gate

Flush Gate is composed of 2 units of the steel slide gate, which is to be manually lifted (Figure. 1). The gate is connected to Hartaco Drainage Channel, which is further connected to 3 main drainage channels, namely Jongaya, Panampu and Sinrijala in Makassar City

Drainage Control Gate

Each of three drainage channels is equipped with drainage control gates .These drainage control gates aim at controlling the flow of drainage channels so as to maximize effects of dilution of the water in drainage channels. All of the drainage control gates are the steel slide gate type, which is to be manually lifted.

During the test operation of Panampu Drainage Channel, the Jongaya and Sinrijala Control Gates were closed and the other way if the test operation is made for Sinrijala Drainage Channel, Jongaya Control Gate is closed and Panampu Control Gate is opened. Under such conditions, the Panampu and Sinrijala Control Gates were opened during the test operation to confirm the effects of the discharge released from Flush Gate for diluting of Panampu and Sinriiala Drainage Channels. The Panampu and Sinrijala Drainage Channel have four and three gate leaves, respectively. The Jongaya and Sinrijala Control Gates were closed, and the Panampu Control Gate was fully opened during the test operation so as to confirm the maximum effects of dilution. During closing of the Jongava and Sinrijala Control Gates, the water is overflowed





A A

UPSTREAM GATE A

SKETCH OF FLUSH GATE

Α

DOWNSTREAM GATE A

PROFILE OF GATE A-A

Fig. 2 Flush Gate Structure

METHODOLOGY

 Clarification on hydraulic conditions of the relevant facilities including measurement of the outflow discharge from Flush Gates, and measurement of the channel flow discharge and velocity of Panampu and Sinrijala,

 Sampling and laboratory test on water quality of Panampu and Sinrijala drainage channels, before and after releasing discharge from Flush Gate;

- Color and smell of water of Panampu and Sinrijala drainage channels before and after releasing discharge from Flush Gate, and
- Issues on operation manual system development

The test operation procedures are as follows :

Bronotony	- Reconnaissance of drainage channel and gates				
Fiepatory	- Closing of Flush Gate/Drainage Control Gates				
	 1st Water quality sampling at Panampu Drainage Channel before opening age Observation of water levels at the upstream of Rubber Dam (+1.60 m), the inlet of Long Storage (+1.54 m) and the inlet of Flush Gate (+1.40 m) 				
	 Opening of Flush Gate and Panampu Control Gate 				
	- 1^{st} Measurement of outflow discharge from Flush Gate (Hartaco channel), - Q = 1.627 m ³ /s and flow discharge of Panampu drainage channel ,Q = 1,231 m ³ /s				
Test Operation of Panampu Drainage	 2nd Water Sampling at Panampu Drainage Channel Observation of water levels at the upstream of Rubber dam (+1.60 m), the inlet of Long Storage (+1.55 m) and the of Flush Gate (+1.40 m) 				
Channel	- 2 nd Measurement of outflow discharge from Flush Gate (Hartaco channel)				
	- Q = 1.984 m ³ /s and outflow discharge of Panampu Drainage Channel , Q = 1.640 m ³ /s				
	 Observation of water levels at the upstream of Rubber dam (+1.60 m), the inlet of Long Storage (+1.55 m) and the inlet of Flush Gate (+1.40 m) 				
	- 3^{rd} Measurement of outflow discharge from Flush Gate (Hartaco channel), Q= 1.815 m ³ /s and outflow discharge of Panampu Drainage Channel , Q = 1.636 m ³ /s				
	- Closing of Flush Gate and Panampu Control Gate				
	 3rd Water Sampling at Panampu Drainage Channel , one day after closing of Flush Gate 				
	 1st Water Sampling at Sinrijala Drainage Channell, before opening of Flush Gate 				
Test Operation of Sinrijala Drainage	 Observation of water levels at the upstream of Rubber dam (+ 1.59 m), the inlet of Long Storage (+1.56 m) and the inlet of Flush Gate (+1.40 m) 				
Channel	- Opening of Flush Gate and Sinrijala Control Gate				
	- 1^{st} Measurement of outflow discharge from Flush Gate (Hartaco channel), Q = 1.958 m ³ /s and outflow discharge Sinrijala Drainage Channel (PM), Q = 1,275 m ³ /s				

Table 1. Test Operation Procedur

	 2nd Water Sampling at Sinrijala Drainage Channel (AM 09:00), one day after opening of Flush Gate 	
	 Observation of water levels at the upstream of Rubber dam (+1.58 m, the inlet of Long Storage (+1.46 m) and the inlet of Flush Gate (+1.38 m) 	
	- 2^{nd} Measurement of outflow discharge from Flush Gate (Hartaco channel), Q = 1.503 m ³ /s and outflow discharge of Sinrijala Drainage Channel, Q = 1.476 m ³ /s	
	 Observation of water levels at the upstream of Rubber dam (+1.58 m, the inlet of Long Storage (+1.45 m) and the inlet of Flush Gate (+1.38 m) 	
	- 3^{rd} Measurement of outflow discharge from Flush Gate (Hartaco channel) Q = 1.446 m ³ /s and outflow discharge of Sinrijala Drainage Channel , Q = 1.389 m ³ /s	
	- Closing of Flush Gate and Sinrijala Control Gate	
	- Data Processing and Discussion	
Data Processing of Discharge Measurement	 3rd Water Sampling at Sinrijala Drainage Channel ,one day after closing of flush gate 	
	- Opening of Flush Gate and Drainage Control Gates	
	- Data Processing and Discussion	
	- Opening of Jongava Control Gate	

RESULT AND DISCUSSION

Measurement of Water Level

There is a small retention pond for the Flush Gate, and a trash-trap screen is

installed at the outlet of the retention pond or 2.5m upstream of the Flush Gate. The staff gauge is also installed between the screen and the Flush Gate as illustrated in Figure 3.



Fig. 3 Gaps of Water Level between Retention Pond and Inflow to Flush Gate

The water for dilution of the drainage channel has the following route: (1) Jeneberang River \rightarrow (2) Long Storage/Retention Pond \rightarrow (3) Trash Rack \rightarrow (4) Flush Gate \rightarrow (5) Drainage Channel. In order to know the flow condition, the staff gauge is installed at the following 4 sites:

- (1) Jeneberang River just upstream of Rubber Dam,
- (2) Jeneberang River at Inlet Gate for Long Storage,
- (3) Long Storage at Inlet Gate from Jeneberang, and
- (4) Retention Pond just upstream of Flush Gate.

The water levels on the above staff gauges were read before discharge measurement of outflow discharge from Flush Gate. The results of reading are as shown in Table 2.

A substantial volume of garbage has been accumulated at the trash rack impeding the smooth inflow from the Long Storage/Retention Pond to Flush Gate. As the results, a gap of 0.2 to 0.3 m was detected between the water level of Long Storage at Inlet Point and the Retention Pond just upstream of Flush Gate, when the Flush Gate is opened releasing the discharge as listed above.

Table 2 Res	sults of Readi	ng of Water	Level on Staff	Gauge
-------------	----------------	-------------	----------------	-------

						(Unit: El. m)
			Jeneberang	Jeneberang		Retention
			River	River	Long	Pond
Ľ	Date	Time	(Upstream	(Inlet Point	Storage	(Upstream of
			of Rubber	to Long	(Inlet Point)	Flushing
			Dam)	Storage		Gate)
Flu	ishing o	f Panampu	Drainage Char	nnel		
1	Nov.	16.35 -	1 60	1 65	1 54	1 40*
	15	16.43	1.00	1.00	1.04	1.40
2	Nov.	14.29 -	1 50	1 67	1 56	1 /0
	16	15.09	1.55	1.07	1.50	1.40
3	Nov.	16.07 -	1 60	1 68	1 55	1 /0
	16	17.01	1.00 1.00		1.55	1.40
Flu	ishing o	f Sinrijala D	rainage Chann	el		
4	Nov.	16.30-	1 50	1 66	1 56	1 /0
	20	17.14	1.55	1.00	1.50	1.40
5	Nov.	14.37-	1 50	1 66	1 46	1 20
	21	15.14	1.30	1.00	1.40	1.30
6	Nov.	16.06-	1 50	1.67	1 15	1 20
	21	16.57	06.1	1.07	1.40	1.30

*: The first water level of retention pond was read just before opening of the Flush Gate, while the second, third, and forth and other water levels are during opening of Flush Gates.

.

Measurement of Flow Velocity and Discharge

The measurement of flow velocity and discharge was made in Hartaco Drainage Channel just downstream of Flush Gate (\pm 40m) and in Panampu and Sinrijala Drainage Channels at 60 m upstream from the Drainage Control Gate. The results of measurements are as shown in Table 3.

The above measured flow discharge could be almost equal to the discharge released from the Flush Gate, and could be also estimated from the following formula:

$$Q = C_*a_*B_*(2g_*h_0-a)$$
(1)

Where:

- Q : Outflow discharge from Gate
- A : Gate opening height (=0.80m)
- B : Gate opening width (= 2.0m)
- G : Gravitational acceleration (=9.8 m/s)
- h_0 : Water depth upstream of the gate
- C : Coefficient (=0.32)

The discharges are calculated by the above formula based on the observed gate water depth at the upstream point of the gate and then compared with the above-observed values. The results of comparison are as shown in Table 4.

		Flow Velocity (m/s)		Flow Depth (m)		Discharge (m ³ /s)		
l	Date	Time	Hartaco	Panampu	Hartaco	Panampu	Hartaco	Sinrijala
			Channel	Channel	Channel	Channel	Channel	Channel
Flu	shing o	f Panampu	Drainage (Channel				
1	Nov.	16.35	-		0.90 -	0.50 –	1 627	1 221
	15	16.43	0.603	0.230	1.00	0.90	1.027	1.231
2	Nov.	14.29 -			0.96 –	0.76 –	1 001	1 6 4 0
	16	15.09	0.664	0.233	1.10	1.10	1.904	1.040
3	Nov.	16.07 -			0.96 –	0.72 –	1 015	1 626
	16	17.01	0.589	0.245	1.12	1.10	1.010	1.030
			Flow Velo	ocity (m/s)	Flow D	epth (m)	Discharg	ge (m ³ /s)
l	Date	Time	Hartaco	Sinrijala	Hartaco	Sinrijala	Hartaco	Sinrijala
			Channel	Channel	Channel	Channel	Channel	Channel
Flu	shing o	f Sinrijala D	Drainage Ch	nannel				
4	Nov.	16.30-			0.94 –	0.74 –	1 050	1 075
	20	17.14	0.664	0.189	1.10	1.09	1.900	1.275
5	Nov.	14.37-			0.86 –	0.82 –	1 502	1 476
	21	15.14	0.549	0.205	1.00	1.17	1.505	1.470
6	Nov.	16.06-			0.89 –	0.79 –	1 116	1 260
	21	16.57	0.527	0.177	1.04	1.24	1.440	1.309

Table 3. Results of Measurements of Flow Velocity and Discharge

No	Data	Time	Water Depth	Gate	Discharge (m ³ /sec) Measured		
No. Date		nme	Gate (m)*	Height (m)	Estimated	Hartaco Channel	Panampu Channel
Pana	ampu D	rainage Cl	nannel				
1	15- 11	16.35- 16.43	1.40	0.80	1.756	1.627	1.231
2	16- 11	14.29- 15.09	1.39	0.80	1.741	1.984	1.640
3	16- 11	16.07- 17.01	1.40	0.80	1.756	1.815	1.636
Sinri	Sinrijala Drainage Channel						
4	20- 11	16.30- 17.14	1.39	0.80	1.741	1.958	1.275
5	21- 11	14.37- 15.14	1.38	0.80	1.726	1.503	1.476
6	21- 11	16.06- 06.57	1.38	0.80	1.726	1.446	1.369

Table 4. Comparison of Estimated and Measured Discharge

*: Water Depth = {Water level of Retention Pond read from the staff gauge as listed in Table 2} - {Elevation of the bottom of the gauge (= EL. 0.2m)}

As listed above, the estimated values could accord to the values actually measured in Hartaco Channel, and therefore, the discharge released from the Flush Gate would be substantially estimated from the above formula, when only the water depth upstream of the Gate is read. This inconsistency would be attributed to water losses (it is assumed due to channel storage, lateral seepage/influent, overflowed water at Jongaya, Panampu and Sinrijala Control Gates were being closed).

Results of Water Quality Test

A particular attention should be, however, given to the inconsistency between the discharges measured in Hartaco and Panampu Channels in No.1 - No.3 and No.5 to No. 6 of test operation as listed in Table 4. In the No.1, 2 and 3 (Panampu Channel), No.4, 5, and 6 of test operation, the discharge measured in Hartaco Channel is far higher than that in Panampu and Sinrijala Channels. As shown in the results of the laboratory test on water quality of Jongaya Drainage Channel listed Table 5, the water quality had been remarkably improved one day after continuation of water releasing from the Flush Gate. However, the water quality one day after closing of the Flush Gate returned to almost same level as that before opening of Flush Gate.

ltem	Unit	<u>AM9:00 on 15-</u> <u>Nov. 2006</u> (Immediately	<u>AM9:00 on 16-</u> <u>Nov. 2006</u> (One-day after	<u>AM9:00 on 18-</u> <u>Nov. 2006</u> (One-day after
	•	before Opening of Flush Gate)	Opening of Flush Gate)	Closing of Flush Gate)
Sampling at Pa	anampu	Drainage Channel		
Temperature	°C	29.5	30.4	30
Turbidity	NTU	94	28.2	28.8
PH	-	6.8	6.3	6.5
Conductivity	ms/c m	1.087	0.478	0.528
TDS	mg/l	543.5	234.1	264.0
TSS	mg/l	56.2	27.4	13.4
BOD	mg/l	2.34	3.00	1.90
COD	mgt/l	23.46	13.32	11.82
		AM9:00 on 20-	AM9:00 on 21-	AM9:00 on 23-
		<u>Nov. 2006</u>	<u>Nov. 2006</u>	<u>Nov. 2006</u>
Item	Unit	(Immediately	(One-day after	(One-day after
		before Opening of	Opening of Flush	Closing of Flush
		Flush Gate)	Gate)	Gate)
Sampling at Si	nrijala D	rainage Channel		
Temperature	°C	29.8	30.7	30.7
Turbidity	NTU	113.2	15.4	38.5
PH	-	6.5	6.3	6.5
Conductivity	ms/c m	1.368	0.254	0.493
TDS	mg/l	683.9	127	246.6
TSS	mg/l	88.5	11.3	31.2
BOD	mg/l	4.68	1.96	3.8
COD	mgt/l	23.4	9.66	17.82

Table 5.Results of Water Quality Test of Panampu and Sinrijala Drainage Channels before and after Opening of Flush gate

Results of Field Observation

The following improvements of Panampu and Sinrijala Drainage Channels by releasing discharge of 1.63-1.98 m³/s (at Panampu) and 1.45-1.96 m³/s from the Flush gates were confirmed through the field observation.

 The discharge of 2.0 m³/s is deemed to be the allowable maximum discharge released from flush gate. Should the Flush Gate release the discharge more than 2.0 m^3/s , there would be a danger to cause the overflow in Hartaco Channel.

The water quality of Panampu and Sinrijala Drainage Channels could be remarkably improved by one-day continuous release of discharge of about 2.0m3/s from the Flush Gate. However, the water quality one day after closing of the gate would return to be almost same as that before releasing of discharge from the gate

- The offensive odor from Panampu and Sinrijala Drainage Channels was much reduced after one-day releasing of discharge.
- The color of the water in Panampu and Sinrijala Drainage Channels was black before commencement of releasing discharge from Flush Gate. On the other hand, the color changed from black to green after one-day releasing of discharge of about 2.0m3/s from Flush Gate
- The improvements in smell and color of water in Panampu and Sinrijala Drainage Channels by twoday releasing of discharge is nil as compared with that by one-day releasing of discharge
- A large number of solid wastes still remain in the drainage channel even after two-day consecutive releasing of discharge.

CONCLUSION AND RECOMMENDATIONS

The conclusion from the test operation are as follows ;

- The contamination of water in Jongaya, Panampu and Sinrijala Drainage Channels is judged to be out of tolerable level, and certain countermeasures against it should be practiced
- The Flush Gate is now usually closed (it is opened only once a year only in August), and the Tidal Gate instead of the Flush Gate is usually kept open during a dry season. Such gate operation aims at pushing the floating vegetation called 'enceng gondok' in

Indonesian toward the downstream of Long Storage by the current from the inlet gate to Tidal Gate.

- As stated above, the drainage channels are seldom diluted by releasing discharge from the Flush Gates. Nevertheless, a certain effect in diluting the water of Panampu and Sinrijala Drainage Channels is confirmed through the test operation, and therefore, the Flush Gate should be opened more frequently on the premises of the following conditions:
 - a. The Flush Gate should be opened once for two days for cleaning of Panampu and Sinrijala Drainage Channels, and should continue to release the discharge for one day. During the time of cleaning of Panampu and Sinrijala Drainage Channels, the control gates of Jongaya Channel should be closed and closing of Panampu and Sinrijala control gates were made by turn.
 - b. The discharge released from the Flush Gate should be about 2m³/s. The adjustment of discharge should be made based on the formula described in the above Sub-section 6.2, and the gate opening height estimated from reading of staff gauge in the Retention Pond.
 - c. In order to allow releasing the above discharge from Flush Gates, the Rubber Dam should be operated to keep its upstream river water level at EL 1.70 m during a dry season. At the same, Bili-Bili Dam should be operated to keep the river maintenance flow of 1.0m³/s along Lower Jeneberang River.

The solid wastes in the drainage channel are hardly removed by discharge released from the Flush Gates. Accordingly, removal of the solid wastes should be made by the alternative methods such as periodical channel dredging works and installation of trash rack across the drainage channel together with periodical removal of the trash accumulated at the screen.

Recommendation;

- The flushing discharge should be maintained constant at the sama or above the drainage sedigned capacity
- Flushing should be performed continuesly for 2 days for each flushing operation
- Flushing operation should be conducted every 2 weeks during dry season
- This procedure should be exercised during dry season in order to develop a permanent procedure for routine flushing
- Bed load should be excavated to meet maximum drain capacity
- Socialization for public awareness
- Testing of well water (ground water) quality

REFERENCES

- 1. JICA (Japan International Cooperation Agency), November 2006, Studi Pengembangan Kapasitas Pengelolaan Sungai Jeneberang di Republik Indonesia
- 2. Chow, Ven Te, "Open Channel Hydraulics", International Students Edition, McGraw-Hill, Kogakusha, Ltd, 1979
- 3. Gupta Ram,S,cs, Hydrology and Hydraulic Systems, 2nd Edition,Waveland Press,Inc, 2001
- 4. Ray K,Linsley, cs.,. Water Resource Engineering ,3rd Edition, McGraw Hill, Inc,1979
- 5. Undang-undang No, 23 Tahun 1997 tentang Ketentuan-ketentuan Pokok Pengelolaan Lingkungan Hidup
- Peratutan Pemerintah No, 27 Tahun 1999 tentang Analisis Mengenai Dampak Lingkungan
- 7. Undang-undang No. 7 Tahun 2004, tentang Sumber Daya Air.